

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY DATAMASTER MAINTENANCE REPORT

RECEIVED COST Breen Accord Program
By Carol Day at 9:43 art, Sep 16, 2009

Complete this report in duplicate at the time of the regular monthly preventive maintenance check, and whenever instrument is repaired. Send copy to Department of Health; retain original in department file.		
DATAMASTER SN 980/3/		DATE OF INSPECTION 09 · 10 · 2009
A CANADA OF INCOME MATERIAL AND	2 /	TIME OF INSPECTION
402 E. MAIN MARTHASVILLE, MC CHECKLIST: Place a check (<) to the left of each item if found	1 63357	within actablished limits. (Write
in observed values where determined.) Unchecked items must be		
☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHED)		
COMPUTER	DETECTOR	en e
☑ PROGRAM	1 FILTERS	
☑ HEATERS SAMPLE CHAMBER 49 °C	QUARTZ STANDARD	
☑ FLOW DETECTOR	CALIBRATION	
☑ PUMP HIGH SPEED	PRINTER	
M INDICATOR LIGHTS		
竹 TIME AND DATE 09.10.09 -	0849	·
SIMULATOR TEMPERATURE (34 °C ± 0.2°C)	34.0c	•
☐ CALIBRATION CHECK -		
Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and must have a		
spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) (USE RECIRCULATION PUMP)		
0.100% STANDARD - MUST READ BETWEEN 0.095% an	4 0 105% INCLUSIVE /AT	# 08400
O.040% STANDARD - MUST READ BETWEEN 0.038% an	d 0.042% INCLUSIVE 1307/Le	# 1203 12.08.2009
(ONLY ONE STANDARD IS TO BE USED PER MAINTENAR		
TEST 2 . 095 TEST 2 5 ,		.096
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)	Adio Inter ferm	(e)
Mumber of refusals, since last waintenance report, and number of Breath tests in each range as follows: (DO NOT INCLUDE SIMULATOR TESTS)		
REFUSALS (004) & (.0509) &	(.1519)	9 (Over.19) 0
List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary)		
Instrument Tested and CARTIFIED WITHIN DHSS		
STAM WARDS		
INSPECTING OFFICER SIGNATURE	PRINT NAME	/
SUT C. 18 Ay House 436	Emmanuel R. H	OUSE
1 PERMIT NUMBER/EXPIRATION DATE 9 2015 3 - 06 25 2011	TELEPHONE NUMBER	937



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 08400 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1204 percent (w/vol) ethyl alcohol. The expiration date for this lot number is December 8, 2009 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.10 percent BAC.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

BOTTLE #1203

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MISSOURI MARTHASVILLE POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 980131 09/10/09

TESTING OFFICER:
HOUSE/RAY
OFFICER I.D.: 436
PERMIT NUMBER: 920153
EXPIRATION DATE: 06/25/11
MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

INTERMAL STANDARD VERIFIED 08:5	4
EXTERNAL STANDARD , 495 98:5	٦
BLANK TEST .000 99:5	ij
EXTERMAL STANDARD ,095 08:5	S
BLANK TEST .000 93%5	ď
EXTERNAL STANDARD .096 08:5	집
BLANK TEST .000 08:5	8

H = 3 SIM. = .1 AVG. = .0953 Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MISSOURI MARTHASVILLE POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 980131 09/18/09 08:49

--- DIAGNOSTIC CHECK ---

COMPUTERS OKAY PROGRAM (04-07-2009): OKAY HEATERS SAMPLE CHAMBER: 490 FLOW DETECTORS OKAY PLMP HIGH SPEEDS OK97 DETECTORS OKRY FILTERS: UKHY QUARTZ STANDARD: OKAY

PRINTER TEST

OKAY

!"#\$%&^()*+.-./0123456789::<=>?eABCDEFG HIJKLMMOPQRSTUVWXYZ[\]^_\abcdefahiJklmno parstuvwxyz(|)*+

Operator Signature SGT House 436 WCSD

CMS

Operator Signature

56T / House 436

CMSU 2208-02

Printed on recycled paper with agri-based inks

CALIBRATIONS

Printed on recycled paper with agri-based inks

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI MARTHASVILLE POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 980131 89/18/89

ARREST TIME: 00:30 SUBJECT HAME: RADIO/FREQ/TEST DOB: 11/11/49 SEX: M STATE/3.L.: MO/123456789 ARRESTING OFFICER: HOUSEZRAY OFFICER 1.D.: 436 TESTING OFFICER: HOUSEZRAY OFFICER I.D.: 436 PERMIT NUMBER: 920153 EXPINATION DATE: 06/25/11 MISCELLAMEOUS INTA:

--- BREATH AMALYSIS ---

WLANK TEST INTERNAL STAMBARD NADIO INTERFERENCE

VERIFIED

Sot House 436 WCSD Operator Signature_

Printed on recycled paper with agri-based inks

CMSU 2208-02

State of Missouri DEPARTMENT OF HEALTH



MO 580-0771 (7-88)

TYPE II



EMMANUEL R HOUSE

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

06/25/09	Wa harm Interim Directo	
Number 920153	Director of State Public Health Laboratory	
Expires 06/25/2011	Margart T. Downelly	
MO 580-0771 (7-88)	Director, Department of Health Lab. 4 (R7-88)	